

Concrete Gallery Roof Restoration

STRUCTURE:	Water Pollution Control Plant
LOCATION:	Thunder Bay, ON
PROJECT DATE:	September 1999
PRODUCT USED:	Qualideck Flexible Coating System
JOB DURATION:	2 weeks
CLIENT:	City of Thunder Bay
CONTRACTOR:	Vector Construction Group



PROJECT DESCRIPTION:

The concrete gallery walkway had deteriorated and was causing leakage into the gallery tunnel below. First the old coating and deteriorated concrete was removed. The surface of the area was then prepared, formed and 2 inches of concrete was poured over it. After 28 days of curing a three part Qualideck flexible coating system was installed over the new concrete. Finally the area was seeded to provide a slip resistant walkway.



CORPORATE OFFICE

474 Dovercourt Drive
Winnipeg, Manitoba, R3Y 1G4
Ph. (204) 489-6300
Fax (204) 489-6033
Email: vector@vectorgroup.com

REGIONAL OFFICES

Manitoba Winnipeg (204) 489-6300
Ontario (North) Thunder Bay (807) 346-4405
Ontario (South) Stoney Creek (905) 662-4020
Saskatchewan Saskatoon (306) 934-3533
Alberta Spruce Grove (780) 962-6778

North Dakota Fargo (701) 280-9697
Nebraska Sioux City (402) 494-9305
Iowa Cedar Rapids (319) 364-5355